CLASSIFICATION BOOK CONTROL OF THE C

## Approved For Release 2003712/22 NGTA 485982 00457 004200650008-0

## INFORMATION REPORT

REPORT CD NO. IEINENITIAT 25X1A

X1A

COUNTRY Czechoslovakia

CONFIDENTIAL

Production at Zbrojovka Brno Factories

DATE DISTR. 16 MAY 50

NO. OF PAGES 2

PLACE ACQUIRED

DATE OF

INFO.

SUBJECT

25X1A

NO. OF ENCLS.

SUPPLEMENT TO REPORT NO.


25X1

THIS IS UNEVALUATED INFORMATION

25X1

25X1

- The SKF (Svenska Kullager Fabriker) factory at Pernstein, near Kaden in northwestern Bohemia, was the property of a Swedish firm prior to its nationalization. At present it belongs to Zbrojovka Brno and is known as factory No. 28.
- 2. Factory No. 28 is located at Pernstein nad Ohri, about five minutes from the railroad station in the direction of the flow of the river. It employs approximately 500 persons, and Ing. Jan Froehlich is the plant director in over-all control. The plant was the only one in Czechoslovakia engaged in the manufacture of ball bearings. After nationalization, the Swedish owners removed their machines and left only those machines which had been purchased by the Germans during the war. As a result, the production of balls for bearings was halted completely, and now the factory produces only mountings for ball bearings and AB (sic) rings for axial and radial ball bearings.
- 3. The monthly productive capacity of the factory is 4,500 to 5,000 mountings for ball bearings in various sizes. Balls and rod steel were frequently delivered to the factory from Sweden, but these deliveries have been stopped. There are about two to three wagonloads of bearings on hand, and also a small stock of Swedish steel. If the production of mountings were to continue at the present rate, it would be possible to supply enough bearings for a period of seven to eight months.
- 4. Production by "automats" (machines requiring no workers) is proceeding fairly well, although an acute shortage of machine steel exists. Twelve "automats" are in operation; six are of the ""liehmann" type, one Russian ("Stankozavod"), and the remainder of German design.
- The need for ball bearings is great, and an inadequate supply of them is causing serious disturbances in Czech industry. The factory is not producing enough ball bearings even to supply nationalized industries. A large quantity of ball bearings, which had been sent to Bata in Sazimovs sti, was returned because of faulty workmanship. Froduction suffers because the material used, which comes from Czechoslovakia itself, is of poor quality. Efforts are concentrated on fulfilling the plan rather than on maintaining quality. Alt ough work with the grinding machines is the chief operation, there are not enough of these machines to keep pace with the polishers.



Approved For Release 20	003/12/22 : CIA-RI	DP82-00457R004	420065000 	8-0	25X1
GENTRAL.	INTELLIGENCE	AGENCY	1		

## CONFIDENTIAL

25X1A

- 6. Attempts are being made to produce ball bearings and valve (sic) bearings in the Zbrojovka factory at Lisne and radial bearings in the Zbrojovka Brno plant at Tynisti nad Orligi.
- 7. Zbrojovka Brno is constructing a large plant at Kysucke Nove Hesto, where they will produce all types of ball bearings. They are handicapped, however, by a shortage of molybdenum and vanadium, which were formerly obtained exclusively from the United States, and of special machinery.
- 3. The Poldina foundry at Kladno is supplying three-meter rods with a bend of L8 cms. The rods are defective and require repairing.

CONFIDENTIAL